



## Schnittholz - Lagerware

B in cm	H in cm	Länge in m									Bemerkung	
		2,5	3,0	3,5	4,0	4,5	5,0	6,0	7,0	8,0		
3,5/8	14				x							Traufenbohlen
6	12	x	x	x	x				x			Halbholz
7	14	x	x	x	x				x			Halbholz
7	18	x	x	x	x				x			Halbholz
8	16	x	x	x	x				x			Halbholz
8	20	x	x	x	x				x			Halbholz
10	12								x			
12	12	x	x	x	x	x	x					auch Kreuzholz
12	14								x			
14	14	x	x	x	x	x	x					auch Kreuzholz

## Bretter und Bohlen

S in cm	B in cm	Länge in m									Bemerkung	
		2,5	3,0	3,5	4,0	4,5	5,0	6,0	7,0	8,0		
1,8	10 - 18	x	x	x	x							
2,4	10 - 24	x	x	x	x	x	x					auch prismiert (12, 14, 16, 20)
3,5	12 - 20				x							
4,0	12 - 24				x							
5,0	28				x		x					

## Latten

B in cm	H in cm	Länge in m									Bemerkung	
		2,5	3,0	3,5	4,0	4,5	5,0	6,0	7,0	8,0		
24	48	x	x		x	x	x					
30	50				x	x	x					
40	60				x		x					